





IM90Xi - IM100Xi





IM90Xi

Ø = 2.5 > 3.1 mm
L = 50 > 90 mm (Smooth & Ring)
RoundDrive®
34°

IM100Xi

Ø = 2.8 > 3.4 mm
L = 63 mm Ring
98 mm Uniloc
100 mm Smooth

RoundDrive®
34°



= 13 000 max



	15 min.	2 500 max.
	60 min.	10 000 max.
	90 min.	13 000 max.



25%	50%	75%	100%
☐	☐	☐	☐
☐	☐	☐	☐
☐	☐	☐	☐
☐	☐	☐	☐











0 → 300
☐
☐
☐
☐



-15°C	IM90Xi / IM100Xi : 1 000 /hour
≤ T ≤	IM90Xi : 4 000 /day
+49°C	IM100Xi : 3 000 /day







RESET



Resting position / Ruheposition / Position de repos / Ruststand / Posición de descanso / Posizione di riposo / Posição de descanso / Pozycja spoczynku / Klidová poloha / Nyugalmi állapot / Положение в нерабочем состоянии / Θέση αδράνειας / Hvilestilling / Viloläge / Hvileposisjon / Lepoasento / Položaj mirovanja / Pokojová poloha / Položaj mirovanja / وضع السكون / Ramybės padėtis / Ootestasend / Miera stāvoklis / Hvíldarstaða

Notes





Paslode
 Impulse®

Route de Lyon F-26500 Bourg-lès-Valence

019690-1
 02/2020